Form 2614 A—Revised Oct. 1933
TREASURY DEPARTMENT
U. S. COAST GUARD

*RADIO LOG* USCGC ITASCA *Date* 1 JULY 1937, 193

| L.G.BELLARTS CRM ON WATCH// ENTRIES 3105 KCS | TIME |
|---|---|
| WATCH STARTED AT// SIGNALS HEARD LOGGED ONLY// | 1900 |
| VERY WEAK SIGS ON 3105 / UNREADABLE AND SEEMED SHIFT ABOUT | 1917 |
| NO SIGS ON DURING PERIOD | 1945/48 |
| WATCH RELD BY GE THOMPSON RM3C LG BELLARTS CRM | 50 |
| NO SIGS ON 3105 | 2015-18 |
| KHAQQ DE NRUI A A A A A NRUI HOWLAND ISLAND A A A A A | 2030-35 |
| UNREADABLE FONE SIGS ON OR ABT 3105 | 35-40 |
| SENT WEA TO KHAQQ ON 7500 | 55-58 |
| KHAQQ DE NRUI A A A A A A NRUI HOWLAND ISLAND A A A A A A | 2100-05 |
| LISTENED FOR KHAQQ ON 3105 ND | 15-18 |
| SENT WEA 7500 | 55-58 |
| SENT WEA 3105/ KHAQQ DE NRUI AAAAA NRUI HOWLAND AAAAAAA | 2130-33 |
| UNREADABLE FONE SIGS ON OR ABT 3105 | 41-43 |
| LISTENED FOR KHAQQ - SEVERAL CARRIERS BUT UNREADABLE | 45-48 |
| GAVE WX TO KHAQQ 7500 | 55-58 |
| KHAQQ DE NRUK A A AAAAAA NRUI HOWLAND ISLAND AAAAAAA | 2200-03 |
| SEVERAL UNREADABLE CARRIERS ON OR ABT 3105 | 03-07 |
| PLANE UNHEARD | 15-18 |
| KHAQQ DE NRUI SENT WEA 7500 | 30-38 |
| KHAQQ DE NRUI AAAAAAA NRUI HOWLAND AAAAAAAAAA | 30-33 |
| LISTENED FER KHAQQ - SEVERAL UNREADABLE FONES BUT CANT MAKE OUT | 45-48 |
| GAVE WX TO KHAQQ ON 7500 | 25-28 |
| KHAQQ DE NRUI AAAAAAAAAA NRUI HOWLAND AAAAAAAAAAA | 30-34 |
| LISTENED FER KHAQQ BUT ND | 45-48 |
| SXXXXXXXXXXXXXXXXQ SENT WEA TO KHAQQ | 55-59 |
| KHAQQ DE NRUI AAAAAAA NRUI HOWLAND AAAAAAAAA | 2300-03 |
| LISTENED FER KHAQQ BUT ND | 15-18 |
| SENT WEA TO KHAQQ ON 7500 | 25-28 |
| KHAQQ DE NRUI AAAAAAAAAA NRUI HOWLAND AAAAAAAAA | 30-33 |
| LISTENED FER KHAQQ ON 3105 ND QRM FONES ES UNREADABLE | 45-48 |
| KHAQQ DE NRUI (GAVE HER OUR WEA ON 7500) | 55-58 |
| KHAQQ DE NRUI AAAAA NRUI HOWLAND AAAA PSE GA 3105 NOW K (UNHRD) | 0000-04 |
| KHAQQ UNHRD | 15-18 |
| SENT WX TO KHAQQ ON 7500 | 25-28 |
| KHAQQ DE NRUI AAAAAAA NRUI HOWLAND AAAAA PSE ANS 3105 (UNHRD) | 30-34 |
| KHAQQ UNHRD | 45-48 |
| SENT WEA TO KHAQQ | 55-58 |
| KHAQQ DE NRUI AAAAAAAAA NRUI HOWLAND AAAAAAAAAA | 0100-04 |
| KHAQQ UNHRD | 15-18 |
| SENT WEA TO KHAQQ | 25-28 |
| KHAQQ DE NRUI AAAAAAA NRUI HOWLAND AAAAAAAAA | 30-34 |
| KHAQQ UNHRD | 45-48 |
| SENT WEA TO KHAQQ ON 7500 | 55-58 |
| KHAQQ DE NRUI AAAAAAAA NRUI HOWLAND AAAAAAAAAA | 0200-04 |
| WATCH RELD BY LG BELLARTS CRM GE THOMPSON RM3C | 05 |
| NOTHING HEARD ON 3105 KCS | 0215-20 |
| SENT WEA ON 7500 | 28 |
| AAAAAAAAA - AAAA NRUI HOWLAND | 30-35 |
| ITASCA TO EARHART / FONE 3105// | 36 |
| HEARD EARHART PLANE / BUT UNREADABLE THRU STATIC | 45/48 |
| SENT WEATHER TO KHAQQ - | 0300 |
| AAA AAA AAA ETC ETC TO KHAQQ/HOWLAND DE NRUI | 04 |

(OVER)

| ENTRIES | TIME |
|---|---|
| REPEATED WX ON FONE// | 030 |
| NOTHING HEARD FROM EARHART// | 15, 18 |
| SENT WX AT | 30 |
| A A A A A A DE NRUI / HOWLAND | 34/ |
| REPEAT WEATHER ON FONE 3105// | 35 |
| EARHART HEARD FONE/ WILL LISSEN ON HOUR AND HALF ON 3105-SEZ SHE | 45/4-- |
| BROADCAST WEATHER FONE 3105// | 0400 |
| REPEATED WEA ON KEY/ 3105 KCS/ | 02 |
| EARHART UNHEARD// | 15/18 |
| BRDSCT WX ON KEY AND FONE// | 30/35 |
| SENT WEATHER /CODE/FONE/ 3105 KCS--(HEARD EARHART -(PART-CLDY)- | 53 |
| -- - - - - - - - - - - - - - - - - | 0500 |
| EARHART UNHEARD// | 15/18 |
| SENT WX AT- FONE KEY- 3105 | 30/35 |
| AAAAAAAAAANRUI TO 7500 KCS// | 40 |
| NO HEAR DURING ((SETTING ON 3105 ALL TIMES// | 45/50 |
| SENT WEATHER / CODE AND KEY 3105 KCS/ | 0600-05 |
| WANTS BEARING ON 3105 KCS// ON HOUR// WILL WHISTLE IN MIC | 14// |
| ABOUT TWO HUNDRED MILES OUT// APPX// WHISTLING// NW | 15 |
| AAAAAAAANRUI (7500)-(LISTENING THRU ON 3105 ) | 30- |
| AAAAA NRUI -- | 35 |
| CALLED EARHART ON 3105 VOICE// | 36 |
| AAAAAAAAAA NRUI NRUI TO //PSE ACKN 3105 | 41 |
| PSE TAKE BEARING ON US AND REPORT IN HALF HOUR-- | 45 |
| I MILL MAKE MOISE IN MIC -ABT 100 MILES OUT | 46 |
| AAAAAAAAAAA 7500 | 0705/ |
| AAAAAAAAA - 3105 | 08/12 |
| AAAAA NRUI ETC// 7500 | 12-14 |
| AAAAAAA NRUI 7500 3105 | 14-16 |
| FONE TO EARHART/ CANNOT TAKE BEARING ON 3105 VY GOOD/ PLESE SEND ON 500 OR DU WISH TAKE BEARING ON US / GA PSE// NO ANSWER | 18 |
| KHAQQ DE NRUI A-S GA 3105 / UNANSWD Stretched off to Gilbert. | 19-24 |
| KHAQQ FM ITASCA PLS GA ON 3105 KCS / UNANSWD / CRM/DC NOW ON THE | 25 |
| KHAQQ DE NRUI A-S GA 3105 / UNANSWD / NRUI'S MAIN D/F 500 KCS | 26-9 |
| KHAQQ FM ITASCA PLS Y OUR SIGS ON KEY PLS / UNANSWD | 30 |
| KHAQQ DE NRUI A-S | 31-4 |
| KHAQQ DE NRUI A-S, 7500 KCS | 35-40 |
| KHAQQ DE NRUI A-S, 3105 KCS | 41 |
| KHAQQ CLNG ITASCA WE MUST ON ØØ YOU BUT CANNOT SEE U BUT GAS IS RUNNING LOW BEEN UNABLE TO REACH YOU BY RADIO WE ARE FLYING AT A 1000 FEET | 42 |
| KHAQQ DE NRUI R MSG R QSA 5 R A-S (500 ES 3105) GA / UNANSWD | 43-6 |
| KHAQQ DE NRUI R MSG R QSA5 R A-S (3105) | 47-8 |
| KHAQQ FM ITASCA UR MSG OK PLS Y WID A3, A3/3105 / A-S FM NRUI A2 | 49-50-57 |
| KHAQQ CLNG ITASCA WE ARE CIRCLING BUT CANNOT HR U GA ON 7500 WID A LNG COUNT EITHER NW OR ON THE SKD TIME ON ½ HOUR (KHAQQ S5 A3) | 58 |
| KHAQQ DE NRUI A-S, 7500 / GA 3105 | |
| KHAQQ CLNG ITASCA WE RECD WX UR SIGS BUT UNABLE TO GET A MINIMUM PSE TAKE BEARING ON US AND ANS 3105 WID VOICE / NRUI DE KHAQQ LNG DASHES ON 3105 / NRUI2 DE NRUI P AR | 0800-3 |
| NRUI2 GIVING TO DPE TT NO SIGS ON 3105 ES IMPOSSIBLE TO WRK ITA / R | 04 |
| KHAQQ FM TTASCA UR SIGS RECD OK WE ARE UNABLE TO HEAR U TO TAKE A BEARING IT IMPRACTICAL TO TAKE A BEARING ON 3105 UR VOICE HW DO U GET TT GA / UNANWD, 3105 | 05 |
| KHAQQ DE NRUI GA ON 3105 OR 500 K, 7500 | 06 |

Form 2614 A—Revised Oct. 1933
TREASURY DEPARTMENT
U. S. Coast Guard

*RADIO LOG* ITASCA *Date* 2 JULY, 1937

| ENTRIES | TIME |
|---|---|
| W L GALTEN, RM3C ON - CGR-32-1 | |
| KHAQQ DE NRUI GA 500 WID DASHES ON 500 K / UNANSWD | 0805-8 |
| KHAQQ FM ITASCA DID U GET TT XMISION ON 7.5 MEGS GA ON 500 KCS SO TT WE MAY BE ABLE TO TAKE A BEARING ON U IMPOSSIBLE TO TAKE A BEARING ON 3105 - PLS ACKNWLDGE THIS XMISION WID A3 ON 3105 GA / UNANSWD | 11 |
| KHAQQ DE NRUI RPTING ABVE INFO ON 7500 / NO ANSWR | 12-14 |
| KHAQQ FM ITASCA DO U HR MY SIGS ON 7500 KCS OR 3105 KCS PLS ACKNWLDGE WID RECEIPT ON 3105 KCS WID A3 GA / UNANSWD | 15 |
| KHAQQ DE NRUI REPTED ABVE DPE ON 7500 GA 3105 A3 AR / UNANSWD | 16-7 |
| KHAQQ FM ITASCA WL U PLS Y OUR SIGS ON 7500 OR 3105 GA WID 3105 A3 | 18 |
| KHAQQ UNANSWD | 19 |
| KHAQQ DE NRUI GA 3105 A3 KCS WID REPORT OUR SIGS | 20-3 |
| KHAQQ DE NRUI GA 3105 KCS WID A3 ES XMIT POSN REPT ES QSA ON OUR SIGS | 24-6 |
| ITASCA TO EARHART WE XMITING CONSTANTLY ON 7.5 MEGS DO U HR US KINDLY CFM RECEIPT ON 3105 WE ARE STANDING BY, A3/3105 | 27 |
| KHAQQ DE NRUI ANS 3105 A3 K / UNANSWD | 28-9 |
| KHAQQ DE NRUI ANS 3105 KCS WITH REPORT ES POSN, XXXX 7500 / UNANSWD | 30-1 |
| EARHART FM ITASCA WL U PLS CUM IN AND ANS ON 3105 WE ARE XMITING CONSTANTLY ON 7500 KCS WE DO NOT HR U ON 3105 PLS AND 3105 GA / UNANSWD | 33 |
| KHAQQ DE NRUI ANS 3105 KCS WID A3 HW OUR SIG QSA? GA / UNANSWD | 34-41 |
| LSNIN 3105 / NIL - CRM TUNIN UP T16 FER XMISION TO NMC | XX 42 |
| NMC V NRUI P AR, 12600 / UNANSWD | XX-43 |
| KHAQQ TO ITASCA WE ARE ON THE LINE 157 337 XX WL REPT MSG WE WL REPT N ES S THIS ON 6210 KCS WAIT, 3105/A3 S5 (?/KHAQQ XMISION WE ARE RUNNING ON XXX LINE | 43 |
| LSNIN 6210 KCS / KHAQQ DE NRUI HRD U OK ON 3105 KCS XX, 7500 | 44-6 |
| KHAQQ DE NRUI PLS STAY ON 3105 KCS DO NOT HR U ON 6210 MAINTAIN QSO ON 3105, 7500 / UNANSWD | 47 |
| NIL ON 3105 OR XX 6210 FM KHAQQ / KHAQQ DE NRUI ANS 3105 KCS | 48 |
| KHAQQ DE NRUI ANS 3105 KCS A3 / UNANSWD | 49-53 |
| KHAQQ DE NRUI UR SIGS OK ON 3105 GO AHEAD WITH POSN ON 3105 OR 500 KCS / UNANSWD | 54-0907 |
| LSNIN 3105 AND 6210/500 KCS / NIL | 08 |
| KHAQQ DE NRUI ANS 3105 OR 500 UR SIGS OK ON 3105 GA WID POSN, 7500 | 09-13 |
| LSNIN 6210 ES 3105 - NIL / 500 NIL | 14 |
| LSNIN 3105, 6210, 500 AND 500 D/F - NIL | 15-33 |
| NRUI2 V NRUI - PER TO, REF HI FREQUENCY D/F, 7500 | 34 |
| KHAQQ DE NRUI GA ON 3105 KCS, 7500 / UNANSWD | 35 |
| NIL FROM KHAQQ / 3105, 6210, 500 OR 500 D/F | 36-41 |
| KHAQQ DE NRUI: XMITING DPE ON ANSWING FREQS / WE CAN HEAR U FINE ON 3105 PLS GA ON 3105, 7500 / UNANSWD | 42-6 |
| NIL FROM KHAQQ | 49 |
| NIL FROM KHAQQ / 3105, 6210, 500 OR 500 D/F | 52-9 |
| NRUI2 V NRUI: - PER TO / GET THE RDO COMPASS WRKING NOW, 7500 | 1002-2 |
| KHAQQ DE NRUI WE HEARD YOU ON 3105 KCS, ETC - 7500 | 03-5 |
| NPM NPU V NRUI V-S ZME / NPM V NRUI INT ZCT KHAQQ INT ZCY KHAQQ AR | 08-10 |
| NRUI V NPM ZZA INT FREQ AR / 3105 / R ZOZ AR / DID U HERE KHAQQ AT ALL AR / ZZA /R THAT T-TO NPU / R (NPM/NRUI - 12600/13380) - PER TO | 12 |
| NRUI V NPM AR / NPM V NRUI RK / BXXR3 B NR3 / R AS | 14 |
| TO ENGAGED NPM: XMITING P MSGS, 12600 | 15-26 |
| DC ENGAGED NPM: RECVING P , 12600 / LSNIN 3105 CONSTANTLY, NIL / BG | 27-30 |
| BG OFF TO DC// | 35 |
| WGEN WGEN DE NRUI NRUI QRU IMI | 38 |
| WGEN WGEN DE NRUI QRU 600 K | 39 |

(OVER)